



PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2011-DAL-0131
Tag #: 3339
JobName:

Date: 7/20/2011

Page 1 of 3

Customer Information

Company Name:	CITY OF FRISCO	Contact:	Lance
Address	ATTN: ACCOUNTS PAYABLES	Telephone:	972-292-5823
	6101 FRISCO SQUARE BLVD	Telephone:	
		Fax:	
	FRISCO TX75034	Email:	

Product Identification

Product Number: Serial Number: 32021800620054

Model:
Impeller Code: 458
HP: 60
Volts: 480
Phases: 3

Inspection Information

Inspected By:		
Motor Data:	Wire Configuration: U1:Red V1:White W1:Black	Sensors:
	Megger to ground: R o B o W o	<input checked="" type="checkbox"/> FLS
	Resistance through cable: RB o RW o BW o	<input type="checkbox"/> CLS
	Stator Condition: Unusable	<input type="checkbox"/> KLIX
	Shaft Condition: Fair	<input type="checkbox"/> Bearing
	Oil Condition: Unusable	<input checked="" type="checkbox"/> Cable
	Inspection Plugs:	Cable Condition: Good
Hydraulic:	Impeller/Propeller Condition: Fair	Cable Length: 40
	Volute Condition: Fair	
Hydraulic Type:	n	<input type="checkbox"/> Control
Installation Type:	p	
Discharge Size:	6	<input type="checkbox"/> MFV

Primary Requirement: bearing locked up ,shavings of bearing housing in stator

Repair/Service Requirements and remarks

shavings in statorfrom bearing housing, stator housing upper bearing housing worn,



PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2011-DAL-0131
Tag #: 3339
JobName:

Date: 7/20/2011

Page 2 of 3

Parts, Labor and Other Charges

Parts:

Qty	PartNo	Description	Total Price
1	607 65 00	HOUSING,STATOR CI	\$4,075.00
1	607 96 00	HOLDER,BEARING ALUM	\$279.00
2	696 16 01	WASHER,SUPPORTING STEEL	\$34.00
1	657 17 03	KIT,REPAIR BASIC 3202.180	\$4,182.00
1	650 51 00	CABLE UNIT	\$54.00
1	663 04 00	SENSOR,LEVEL FLS-10	\$239.00
1	650 84 00	LEAD-THROUGH UNIT	\$107.00
1	6071101-X	STATOR, REMOVED REPAIRED AND RE-INSTALLED	\$2,570.00
		Total Price	\$11,540.00

Labor and Other Charges:

Qty	PartNo	Description	Total Price
11	14-69 98 12	LABOR,SERVICE-CARROLLTON	\$1,067.00
1	14-69 98 34	ENVIRONMENTAL FEE 11-50HP	\$51.00
1	14-69 98 02	MAT'L,LUBES,SOLVENTS-LARGE PUMP	\$62.00
		Total Price	\$1,180.00

Total Price: \$12,720.00

Product Replacement

Product Number: 3202.180-1924

Estimated Delivery: 0 Weeks

Cost of New Unit: \$27,849.00 + \$400 freight = \$28249.00

Description:

Flygt Model NP-3202.180 6" volute Submersible pump equipped with a 460 Volt / 3 phase / 60 Hz 60 HP 1750 RPM motor, 458 impeller, 1 x 50 Ft. length of SUBCAB 4AWG/3-2-1-GC submersible cable, FLS leakage detector, volute is prepared for Flush Valve

Terms

Please note: If additional repair requirements are identified during service, the total cost of your repair may change.

Should this occur, we will contact you for approval before proceeding.

A signed Purchase Order or approval below must be received before any repair work can begin.

If repaired unit is not picked up or delivered within 5 days of completion, the repair will be invoiced.

Time of delivery: Approx. 4 to 5 working weeks after receipt of order.

Terms of payment: Net 60 Days

Validity: This Quote is valid for sixty (60) days.

Exclusions: This Quote includes only the items listed specified above.



PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2011-DAL-0131
Tag #: 3339
JobName:

Date: 7/20/2011

Page 3 of 3

Thank you for the opportunity to provide this quotation. Please contact us if there are any questions.

Nate Castillo
Phone: 972/418-2400 Ext. 124
Fax: 972/416-9570
Email: nate.castillo@itt.com

Customer Approval

Complete and sign this Approval and return to ITT Water & Wastewater with, or in place of, your Purchase Order

I authorize ITT Water & Wastewater to proceed for the amount shown above. Repair Replacement

Customer Name: _____ Date: _____

Customer Signature: _____ PO #: _____

Ship To: Will Pick Up Deliver Ship To

Ship/Delivery Address:

Bill To:

Taxable: Yes No

Tax Exemption Certificate must be on file or tax will be applied to the invoice.